

Cutting List

The Cutting List gives finished lengths for the top, front, sides, cleats and bottom. You can cut these to the exact width and length listed and nail them together. The lengths listed for the 3/4-in. x 1-in. bands and the 3/4-in. cove moldings are oversized. You'll mark these pieces in place for an exact fit (Photo 1).

KEY	QTY.	SIZE & DESCRIPTION
A	1	3/4" x 5-1/2" x 36" (top)
B	1	3/4" x 3-1/2" x 32" (front); miter both ends at 45°
B2	2	3/4" x 3-1/2" x 3-1/2" (sides); miter one side
C	1	3/4" x 1-1/4" x 30-1/2" (cleat); 30-degree bevel
D	1	3/4" x 1-1/4" x 30" (cleat); 30-degree bevel
E	1	3/4" x 2-3/4" x 30-1/2" (base)
F	1	1/4" x 2-1/2" x 30" (plywood spacer)
G	1	3/4" x 2-1/2" x 30" (bottom)
H	1	3/4" x 1" x 36" (band); miter both ends to fit
H2	2	3/4" x 1" x 6" (bands); miter both ends to fit
J	1	3/4" x 3/4" x 36" (cove); miter both ends to fit
J2	2	3/4" x 3/4" x 6" (coves); miter both ends to fit
K	1	3/4" x 3/4" x 36" (cove); miter both ends to fit
K2	2	3/4" x 3/4" x 6" (coves); miter both ends to fit