


# FIG. B

1-5/8" GALV. SCREWS THROUGH  
J AND K (PREDRILL ALL)

1/8" GAP  
(TYPICAL)



KEEP 1" BETWEEN EDGE OF  
TOP AND ALL SUPPORTS